

UNPAVED ROADS ON 2005 BOND LIST - JUNE 2008 INVENTORY												
		Rating System:	5 = Excellent	4 = Good		3 = Fair	2 = Poor	1 = Failed				
ROUTE	Traffic Count	ROAD NAME	DESCRIPTION (From / To)	LENGTH (miles)	District	18-foot travel width (two lanes)?	Passable?	Flooding / # Homes Isolated	# Homes on Unpaved portion (side streets)	Candidate for VDOT Maintenance	Comments	Overall Rating
656	560	Towles Mill Road (North)	1 Mi S. Rt 691 / 0.7 MI N. Rt 614	1.20	Berkeley	Yes	Yes	Yes	43 (13)		Little or no gravel layer, moderate washboarding in some sections, shallow ditch needs improvement.	2
656	390	Towles Mill Road (South)	0.81 MI N. Rt 614 / Rt. 614	0.81	Berkeley	No	No	Yes	19		Little or no gravel layer, no ditch. Tree's close to road. Some rutting. No shoulder. Box culvert needs to be replaced.	2
617	340	Ham's Ford	Rt. 605 / Rt. 645	0.85	Berkeley	No	Yes	Yes	23		Little or no gravel layer, no ditch, some rutting on side of road.	2
692	250	Sunnybrooke Farm Road	Rt. 608 / Dead End	0.58	Livingston	No	No	Yes	11 (14)		Little or no ditch. Gravel layer appears adequate. Widening needed. Entrance off Courthouse Road inadequate. Trees close to road.	2
666	170	Tribble Road	Rt. 658 / Dead End	0.78	Berkeley	No	No	No	17		Very narrow, little or no ditch. Large pipe under stream. Little or no gravel.	2
690	84	Pepper Tree Road	Dead End / 0.4 mi N Dead End	0.40	Livingston	Yes	Yes	Yes / 3	3		Surface deformation. Numerous ruts and poor drainage. Road washes out in places. Large concrete pipe needed. Has cul-de-sac.	2
693	70	Glady Fork Road	Rt. 608 / Dead End	0.40	Berkeley	No	No	No	7		Very narrow, no ditch. Shoulder improvement needed.	2
623	52	Stewart Road	Rt. 613 / Rt. 612	0.90	Livingston	Yes	Yes	Yes	5		Visible surface distress - rutting. Poor drainage. Poor gravel surface. Road washed out in places. Needs two (2) large concrete pipes.	2
659	450	Lanes Corner Road	Rt 208 / Rt. 606	2.75	Livingston	No	Yes	No	40 (5)		Surface deformation - rutting at edge of roadway, moderate washborading in center of road. Driveway pipes needed. Shallow or no ditch. Cul-de-sac present.	3
665	430	Belfonte Road	0.6 mi E. Rt. 601 / Dead End	0.84	Livingston	No	Yes	No	43 (4)	Yes	Tree's encroaching on roadway - need trimming. Surface deformation - ruts on edge of road. Pipes needed at residentail driveways. Gravel surface poor in spots. Cul-de-sac present.	3
643	300	Williams Lane	Rt. 601 / Dead End	1.05	Livingston	No	Yes	No	30		Adequate gravel surface and good crown. Road necks down. Needs cul-de-sac.	3
620	277	Spotswood Furnance Road	Rte. 1696 / Rte. 1733	1.30	Livingston	Yes	Yes	Yes	0		Poor gravel surface. Shallow ditch. Needs large concrete pipe. Pipe appears stopped up causing erosion of road. Two wooden bridges along this section.	3
642	260	Woolfolk	Rt 612 / Dead End	0.90	Livingston	Yes	Yes	No	26		Good gravel surface. Shallow ditch needs improvement. Church parking lot flush to the road.Cemetary present. No cul-de-sac.	3
647	130	Twilight Lane/Blaydes Corner	Rt. 605 / Dead End	0.43	Livingston	Yes	Yes	No	10 (13)	Yes	Road narrow in some sections, little or no gravel, shallow or no ditch. Ends in cul-de-sac.	3
696	110	Sullivan Road	Rt 606 / Dead End	0.74	Livingston	No	Yes	No	11	Yes	Good crown. Gravel surface poor in spots. Some potholes. Pipes needed for driveways. Shallow ditch. Cul-de-sac present. One large concrete pipe over culvert.	3
703	90	Mastin Lane	Rt. 649 / Dead End	0.20	Livingston	No	Yes	No	8 (1)	Yes	Shallow or no ditch. Gravel surface poor in spots. Driveway pipes needed.	3
682	80	Parker Lane	Rt. 611 / Dead End	0.95	Livingston	No	Yes	No	8	Yes	Surface deformation - several small potholes. Some areas with little gravel or no gravel. Shallow ditches. Cul-de-sac present.	3
732	70	Mallard Point Lane	Rt 627 / Dead End	0.27	Berkeley	No	Yes	No	7		Shallow ditch. No shoulders. Tree's within ROW. Gravel surface is adequate. Cul-de-sac present.	3

ROUTE	Traffic Count	ROAD NAME	DESCRIPTION (From / To)	LENGTH (miles)	District	18-foot travel width (two lanes)?	Passable?	Flooding / # Homes Isolated	# Homes on Unpaved portion (side streets)	Candidate for VDOT Maintenance	Comments	Overall Rating
726	64	Ryland Payne Road	SR 208 / Rt. 1	0.60	Livingston	No	Yes	No	4		Surface deformation - potholes near driveway entrances, ruts at edge of roadway. Poor or no shoulder. Needs ditch. Gravestones near Lewiston Road.	3
724	52	Wigglesworth Road	Rt. 658 / Dead End	0.47	Berkeley	No	No	No	5		Very little gravel. Narrow road.	3
762	32	White Shop Lane	Rt. 719 / Dead End	0.20	Berkeley	No	Yes	No	2		Good gravel surface. Shallow ditch needs improvement. Cul-de-sac present.	3
643	190	Haleys Mill Road	Rt 601 / Rt. 655	2.25	Livingston	Yes	Yes	No	19	Yes	Adequate gravel surface and good crown. Road necks down. Tree's within ROW. Pipes needed at driveways. Shallow ditch. Needs cul-de-sac.	4
749	169	Old Telegraph Road	Rt. 1 / Dead End	0.43	Lee Hill	Yes	Yes	No	4		Good crown, adequate gravel layer. Ends in cul-de-sac.	4
F697	130	Lavue Lane	Frontage Road Rt. 608 / EOM	0.37	Berkeley	Yes	Yes	No	10 (3)	Yes	No crown. Some potholes. Road necks down. Ditch along Rte. 17 needs to be cleaned out. No ditch visible on opposite side of road.	4
664	76	Granite Springs Road	Rt. 601 / Rt. 680	0.90	Livingston	Yes	Yes	No	6	Yes	Good gravel surface. Most driveways have pipes. Ditches need improvement - too shallow. Large galvanized road pipe needs to be replaced. Narrow wooden bridge on road.	4
651	70	Houston Lane	Rt. 601 / Dead End	0.19	Livingston	No	Yes	No	7		Adequate gravel surface. Needs driveway pipes and cul-de-sac.	4
701	60	Rumsey Drive	SR 208 / Dead End	0.57	Livingston	Yes	Yes	No	6		Adequate gravel surface and good crown. Needs ditch and pipes at driveway entrances. Concrete pipe present at approximate middle of road section. Needs cul-de-sac.	4
754	43	Hayden Road	Rt. 684 / Dead End	0.19	Livingston	No	Yes	No	3		Adequate gravel surface. Shallow ditch. Cemetery very close to road.	4
F168	20	Clark Court	Frontage Road Rt. 608 / EOM	0.130	Battlefield	Yes	Yes	No	2		No crown, Gravel adequate. Washout area near some residences. Ends in cul-de-sac.	4
721	590	Grand Brooks	Lawyers Rd to 1.25 Mile North	1.25	Livingston	Yes	Yes	No	59		Good gravel surface. Good crown and road width is adequate.Church and cemetery in vicinity of road.	5
721	590	Grand Brooks	1.25 Mile North Lawyers to Stubbs Bridge	2.76	Livingston	Yes	Yes	No	59		Good gravel surface. Good crown and road width is adequate.Church and cemetery in vicinity of road.	5
723	122	Dovey Road	Rt. 612 / Dead End	0.60	Livingston	Yes	Yes	No	5		Good crown. Adequate gravel layer. Washboarding present in some sections. Ends in cul-de-sac.Portion of the road is already paved.	5
687	90	Shirley Road	Rt. 653 / Orange CL	1.15	Livingston	Yes	Yes	No	9		Good crown. Adequate gravel surface. Orange County end is paved.	5
759	30	Orrock Road	FR 163 / Rt. 759 Caroline	0.70	Berkeley	Yes	Yes	No	3		Good crown and drainage. Good gravel surface.	5
720	21	Confederate Cemetery Dr.	SR 208 / Dead End	0.57	Berkeley	No	Yes	No	0		Good drainage. Good crown. Check with "Daughters of the Confederacy" on whether this road should be included on this list.	5
757	11	Moss Lane	Rt. 601 / Dead End	0.27	Berkeley	Yes	Yes	No	1		Good crown, gravel needed. Some grass growing in centerline of roadway. Road services one very old home.	5
F163	10	Mallard Road	Frontage Road Rt. 608 / EOM	0.56	Berkeley	Yes	Yes	No	0		Narrow to a single lane in some sections. Excellent gravel layer. Good crown. Ditch needs to be improved.	5
				29.51								